Intuitive user interface

The user interface facilitates parts management with easy-to-identify illustrations and quick access to ribbon menu items, providing you with Windows-like usability for measurement.

See video from here ▶

Graphical display

Measured components are displayed with 3D graphics. In GD&T evaluation, the trend of deviations of the components is simply visualized in the form of a color distribution.

See video from here ▶

Various report formats

GEOPAK includes a range of report templates as standard. There is also support for the display of GD&T icons and graphic display of deviations. In addition, GEOPAK supports inspection reports conforming to the aerospace industry's quality management standard AS 9102 (SJAC9102).